

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/Ala Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021969**Date Inspected:** 11-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes	No N/A
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes	No N/A
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes	No N/A
Approved Drawings:	Yes No N/A	Approved WPS:	Yes	No N/A
		Delayed / Cancelled:	Yes	No N/A
Bridge No:	34-0006	Component:	OBG Components	

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.

Bay 14

This QA Inspector proceeded to Bay 14 in response to ZPMC request #08519 for magnetic particle testing (MT) inspection of the following:

This QA Inspector performed random visual testing (VT) and then MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member was identified as follows: OBG, DP3161-001. The weld designations reviewed were: 017, 018, 023, 041, 042, 049, 050, 057, 058, 065, 066, 087, 088, 095, 096, 103, 104, 111, 112, 133, 134, 141, 142, 149, 150, 157, 158, 179, 180, 187, 188, 195, 196, 203, 204, 074~083, 120~129, 166~175, 040, 043, 048, 051, 056, 059, 064, 067, 086, 089, 094, 097, 102, 105, 110, 113, 135, 140, 143, 148, 151, 156, 159, 178, 181, 186, 189, 194, 197, 202, 205, 218, 221, 226, 229, 234, 237, 242, 245, 220, 227, 228, 235, 236, 243, 244. No apparent indications were observed.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

No significant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George
----------------------	---------------

Quality Assurance Inspector

Reviewed By:	Riley,Ken
---------------------	-----------

QA Reviewer
